

BUILDING SAFETY CERTIFICATE

No: 376 | 2023-24.

Dated: 22/01/2024


Certified that the existing building **WINMORE ACADEMY** (Name Of The Building Or Premises) at No.13/1, Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bengaluru-67 (address) Comprised of Ground and First Floors Owned /Occupied by Winmore Academy, No.13/1,Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bengaluru-67(name of the instution)have complied with the Building Safety requirements in accordance with National Building Code Rules and Verified by the Officers Concerned Of Public Works Department (PWD) on Dated:10.01.2024 (Date Of Inspection) in the Presence Of Principal,Winmore Academy, No.13/1, Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bengaluru-67 (name and addresses of the Manager/Secretary or his representative)and that the building /premises is Fit for Occupancy upto Classes X (10th Standard) (X/XII) With Effect From an Period Of 3 Years in Accordance With test Conducted and Issued Building Safety Certificate by HENCON ASSOCIATES.Bengaluru on 23.11.2021 rule and Subject to Compliance of the Specific Condition as appended

1. Non-Structural Elements (Infrastructural Facilities) like Health Certificate.
2. Fire Safety Certificate has to Endorsed.
3. Drinking Water and Sanitary Certificate Has tobe Endorsed by RWS Department.

Issued on 22.01.2024 at PWD Sub Division Hoskote-562114 by

(Sagar.C.)

Assistant Engineer.
PWD,SubDivision,Hoskote



(Prakash.T)

Assistant Executive Engineer.

PWD,Sub Division ,Hoskote

ನವಾಧಿಕಾರಿ ಕಾರ್ಯಾಲಯ, ನಂದಿಬೆಂದಿ

ಬೆಂಗಳೂರು-562114

ಪುನಃ ಪರಿಶೀಲನೆ ಸಂಖ್ಯೆ-562114

Principal
Winmore Academy
Survey No. 13/1,
Bhaktharahalli Village, Nadavathi Post
Taluk, Bengaluru - 560 067